



WARNING!

Please do not over tighten mounting screws, it could cause damage to the internal tinsel lead.